



S-02 Building Section 1:20




Generic Axonometry 1:200


Notes:

1. Each Mass hand washing facility should have a stop gate a manhole for isolation it case it gets a problem

2. plumbing should have a waist and bottle trap for ublocking the system



0. Floor Plan 1:20



S-01 Building Section (1) 1:20

unicef for every child

Project:	**Upgrade of WASH facilities in Schools**
Drawing Title:	**Mass hand washing facility for tall children**
Drawn by:	**Moses Grace Luwangwa**
Checked by:	
Approved by:	
Date of revision:	March 2020